- Site Service Report -

September 26, 2012

IRD SO#: 11167 IRD Ref: To: ESS

Project Name:LTTP Bemidji, MN

Project Location: Highway 2 Mile 91.5

Service Date(s): May 25, 2010

Weather: 15°Celsius

Job Description: Maintenance

Work Completed:

- Loops, kistlers, piezos and cabinet visually inspected -see attached pictures-
- LANE 1 KISTLER DAMAGED, TOP COVER MISSING (EASTBOUND).
- iSINC components working as expected
- Powered down iSINC to remove each card and cleaned slots and connectors
- Tested each bank of kistlers
- Megged out loops
- Checked VAC and VDC sources, all within parameters.
- Powered back on the iSINC and observed LED activity (working right)
- Connected laptop and observed activity (working right)
- Vehicle records displayed as expected.
- Left site and iSINC running as expected.

Work Remaining: REPLACE LANE KISTLERS

Parts Used: None

Mileage / Travel Time: 486MI / 8 hrs

Time Spent on Site: 4 hours

Notes:

Action Items:

Item	Action Required	Ownership
1.	INSTALL NEW KISTLERS FOR LANE 1 (EASTBOUND)	JORGE